


AKA-- Putt Putt

Owner Comments:

It still won't full stall 3 point with VG's on the wing

Owner says bottom of wing is 18 degree, math shows 17.53 degrees so very close.

It stalls at 30 degrees. This would take a much taller landing gear and is good the way it is.



PROPRIETARY AND CONFIDENTIAL
 THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF <INSERT COMPANY NAME HERE>. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF <INSERT COMPANY NAME HERE> IS PROHIBITED.

		DIMENSIONS ARE IN INCHES		NAME	DATE
		TOLERANCES:			
		FRACTIONAL ±			
		ANGULAR: MACH ± BEND ±			
		TWO PLACE DECIMAL ±			
		THREE PLACE DECIMAL ±			
		MATERIAL	--		
		FINISH	--		
NEXT ASSY	USED ON				
APPLICATION	DO NOT SCALE DRAWING				

DRAWN		
CHECKED		
ENG APPR.		
MFG APPR.		
Q.A.		
COMMENTS:		

Iron Design L.L.C.

SIZE	DWG. NO.	REV.
A		
SCALE:1:100	WEIGHT:	SHEET 1 OF 1